

english
stub

RF Board Test & Fehlersuche

Note: ToDo

Some general hints [here](#)

Symptom: No reception on any band

Note: ToDo: In text below: adapt component numbers once OVI40 RF board schematics are public. Component numbers mentioned now are mcHF specific

Touch certain points on the RF-board with a multimeter test-cord, a piece of cable or similar. A test-cord with measuring tip is well suited for this. Please listen to audio out (speakers or headphones) while doing this.

If there is no sound when touching the base of Q1 there certainly is a hardware problem. This could also have something to do with the mixer or local oscillator. In case there is also no sound when touching the collector of Q1 then this indicates a mixer problem, an issue in the subsequent operational amplifier or in the audio codec including its switching mixer. Since the signal path after the mixer is low frequency audio this can also simply be verified by touching with a finger for initial empirical testing.

From:
<https://www.amateurfunk-sulingen.de/wiki/> - Afu - Wiki des DARC OV Sulingen I40

Permanent link:
<https://www.amateurfunk-sulingen.de/wiki/doku.php?id=en:ovi40test:rfboardtest&rev=1518017760>

Last update: **07.02.2018 15:36**

